

Review Sec. Co. R. ^{531/532} 56/55 T225 R9W

Fd. O.B.T.S as follows -

ORIG. 30" Now 40" cedar N, 65° E. 37° ft.

Now Decayed STump - we find partial axe notch - no scribe Fd. unable to get Ring count.

ORIG. 36" Now 52" cedar N, 30° W. 69³ ft.

2 live - previously opened no scribe we open higher & find top of old axe Blaze & open lower & find axe notch under 85 + years Ring count. NO

Trace other B.T.S - call north to creek fits well - set 1" I.P. &

BRASS cap MKd. "COUNTY SURVEYOR'S

OFFICE 1968 T225 ^{531/532} 56/55 T235

R9W" & MK. New B.T.S -

22" Hemlock N, 22° W. 17° ft.

Mkd. "T225 R9W S 31. CS BT"

24" Hemlock N, 7° E. 18⁷ ft.

Mkd. "T225 R9W S 32 CS BT

35" Hemlock S, 77° W. 65⁸ ft.

Mkd. "T235 R9W S 6 CS BT"

22" Hemlock S, 44° E. 25° ft.

Mkd. "T225 R9W S 5 CS BT"

Jan 4, 1968

V.R.T.

J.H.

V.P.

Ray

O.N. J. W. B. C.S. No. 54/60-23