

Renew Sec. Cor.  $\frac{515}{522} / \frac{514}{523}$  T225 R9W

Fd.  $\frac{5}{8}$ " I.R. FOR COR. (see Ren. #38") & B.T.S  
as follows -

ORIG. 12" Now 36" FIR N.  $65^{\circ}$  E. 21  $\frac{1}{2}$  ft.

alive - shows SCAR - Rescribed in BARK  
by Haines "514 T225 R9W BT" & Haines Butt

ORIG. 16" Now 40" FIR S  $22^{\circ}$  W. 66  $\frac{0}{2}$  ft.

alive - shows good SCAR

ORIG. 16" Now approx 24" FIR N.  $19^{\circ}$  W. 49  $\frac{5}{2}$  ft.

Down - scribe visible - No Trace S.E. BT.  
Haines' BT. 4" FIR N.  $51^{\circ}$  W. 23  $\frac{0}{2}$  ft.

Blaze Pichted over - scribe visible

Haines' Button above blaze. Set 1" I.P.

& BRASS cap at cor point in place of

F.R. & MKd. "COUNTY SURVEYORS OFFICE

1968 T225  $\frac{515}{522} / \frac{514}{523}$  R9W" & MK. New  
B.T. -

8" D. FIR S.  $75^{\circ}$  E. 59  $\frac{8}{2}$  ft.

Mkd. "T225 R9W S 23 CS BT"

Reset I.R. along side BRASS cap. This  
COR. Lies on very steep south slope  
approx 180 ft N. of creek course W.

Jan. 29, 1968

VRT  
J.H.  
V.P.



D.K. J.W.B.  
C.S. File No.

54/60-28