

Review $\frac{1}{4}$ cor $\frac{514}{523}$ T238 R9W

Fd. Remains of O.B.T.s as follows -

orig. 10" Maple S. 40° E. 5 $\frac{3}{4}$ ft.

Down - Badly decayed - fragmentary

Reverse scribe on edges of blaze.

orig. 16" cedar N. $69\frac{1}{2}^{\circ}$ W. 29 $\frac{2}{3}$ ft.

only decayed stamp 8" high - Log

mostly decayed away - No scribe Fd.

SPUR Ridge call to East fits Record

Dist. - at cor. point set 1" I.P.

& Brass cap MKd. "COUNTY SURVEYORS'

OFFICE 1769 T235 $\frac{1}{4}$ $\frac{514}{523}$ R9W"

MK. New B.T.s -

8" Hemlock N. 72° W 28 $\frac{6}{8}$ ft.

MKd. " $\frac{1}{4}$ 514 CS BT"

24" D. Fir S. 75° E. 22 $\frac{6}{8}$ ft.

MKd. " $\frac{1}{4}$ 523 CS BT"

This cor. lies on SW. Slope

80 $\frac{2}{3}$ ft. west of Top of SPUR

Jan. 12, 1970

V.R.T.
J.F.H.
V.O.R.

V.R.T. Ray

D.M.
S.W.D.

#56

C.S. File No. 5460-47