

Renew  $\frac{1}{4}$  COR.  $\frac{527}{534}$  T235 R9W  
Fd.  $\frac{1}{2}$ " Steel Tube at cor. &  
O.B.T.s 25 follows - See Ren. #32  
Orig 24" Now 26" FIR N. 53° W. 16  $\frac{5}{8}$  FT  
Down - Badly decayed - No scribe Fd.  
Orig. 20" Now 29" FIR S. 32° W. 17  $\frac{8}{8}$  FT  
Alive - we open & find. "534" scribe  
at cor. point set 1" I.P. & BRASS  
cap MKd. "COUNTY SURVEYORS  
OFFICE 1970 T235  $\frac{1}{4}$   $\frac{527}{534}$   
R9W" Reset steel Tube alongside  
MK. New B.T.s -

19" D. FIR S. 51° W. 27  $\frac{3}{4}$  FT.

Mkd. " $\frac{1}{4}$  534 CS BT"

30" D. FIR N. 61° E. 25  $\frac{1}{2}$  FT.

Mkd. " $\frac{1}{4}$  527 CS BT"

This cor. lies on nearly flat  
Bench on Easterly slope of  
MTN, also weyerhueser B.T.  
30" FIR N. 53° W. 36  $\frac{3}{8}$  FT. "W" & Plate.

June 1970

U.R.T  
V.D.P.

U.R.T Ray

0#61

0.4  
7.2.73