

58/59
Renew Sec. Cor. 517/516 T235 R9W

Fd. STumps of Q.B.T.s as follows -
ORIG. 30" Now 40" FIR N, 9°W, 52 1/2 ft,
sawed stump - partial axe Blaze on BARK
chopped open by someone - No scribe
Fd. also has old Yellow Tag dated
1945 - & Numerous BRASS MKs.

ORIG. 26" Now approx. 36" FIR S, 54°E, 33 1/2 ft,
Badly decayed & Burned - No scribe Fd.

ORIG. 40" Now 48" FIR N, 89°E, 47 1/2 ft,
Badly decayed & Burned - No scribe Fd.

No Trace of Q.B.T. to SW. - call of
2 chains to East was on trail
I assume trail was on Ridge Top
The approx. 60 ft. elev. Below
Top of Ridge also looks ok -
call on creek to South fits
o.k. by pacing - This position
has been Recognized as cor.

point for at least 25 years
also find Remains of very old
& Badly decayed square post - at
COR. point set 1" I.P. & BRASS
MK. COUNTY SURVEYORS OFFICE

58/59
1970 T235 517/516 R9W " & MK. New Q.T.S. -

#62

(over)

C.S. File No. 54/60 18

New B.T.S -

10" D. FIR S. 19° W. 10⁰ FT.

Mkd. "T235 R9W S17 CS BT"

16" D. FIR S. 76° E. 12⁵ FT.

Mkd. "T235 R9W S16 CS BT"

18" D. FIR N 31° W. 23⁰ FT.

Mkd. "T235 R9W S 8 CS BT"

11" D. FIR N. 26° E. 40³ FT.

Mkd. "T235 R9W S 9 CS BT"

This cor. lies on steep westerly
slope in dense brush -

June 9, 1970

VRT
VDP

~~VRT~~

0.5
5.9