

Renewal $\frac{20}{29}$ / $\frac{21}{28}$ T325 P8W
Found

Brass cap at sec cor MKD
U.S. Cadastral Survey
U.S. B. d. 171

$\frac{20}{29}$ / $\frac{21}{28}$
1959

ORTS

18" D. Fir Now 30" S20W 38 $\frac{3}{4}$
Faint Bark Scribe "S29" "R"
22" D. Fir Now 35" N5E (Rec N5W) 19 $\frac{1}{2}$
(Rec 15-8)
Faint Bark Scribe "S R 73"
New Bark Scribe T32 P8W S21 BT
New BT.
19" cedar Now 14" N38W 56 $\frac{0}{2}$
Scribe visible T32 P8 S20 BT

DIETZGEN NO. 389-6

Renewal

New Bearing Tree
8" Chingupin S85E 57 $\frac{4}{8}$
Scribed T325 P8W S28 CS BT
Reblazed & Rescribed
30" D. Fir S20W 38 $\frac{3}{4}$
Scribed T325 P8W S29 CS BT

Note:

This cor lies in fill approx
20' North of old rd.

5-15-58
~~4-22-58~~
~~4-22-58~~

*9P o.k. J.W. 13

C.S. File No. 54785-13