

Renewal

539
53/52

T325
T335 RBW

Found

Stone 1/2 MARKS visible

14" diameter 5 to 1/2 W 59°
Shows good scan

36" D. Fir Now 5 to 6 S 10 E 18 E
Scribe visible but not indigible

Renewal

Set Brass cap at Sec cor MKD

County Surveyors Office

2325 RBW
Davy, Co.

539 G.C.
53/52
JOS. CO
1968

New Bearing Tree

7" D. Fir 58 W 19 E
Scribed T335 RBW 53 CC CS 27

2" D. Fir 57 1/2 W 17 E
Scribed T335 RBW 53 CC CS 27

No Trees To SE.

Note:

This cor lies approx. 295[±] West
of ~~33/35~~ also about 30' south of
small Ravine - Section #89

5-~~8-68~~
~~JOS~~
~~200~~

D.K.

#92

J.W.B.

C.S. File No. 53/65-14

DIETZGEN NO. 386-B