

Renewal

21/22
18/27

T323 RBW

Found:

8" D. Fir Now 16" S60E 93

This tree had been opened but
buried in fill of Rd. Dug out to
find part of BT.

All other trees gone from
Rd. const.

Renewal

Set Brass cap at sec cor MAD
county Surveyors office

T323 RBW

521 | 522
528 | 527

1968

New Bearing Trees

12 Laurel
Scribed T323 RBW S30W CS 82

20" D. Fir
Scribed T323 RBW S21 CS 87

10" Laurel
Scribed T323 RBW S22 CS 87

Reblazed & Rescribed

16" D. Fir
Scribed T323 RBW S27 CS 87

Note

Cor lies approx. 60° West of
Rd.

3-16-68

#87 O.K. J. W. B.

C.S. No. 52/524

DIETZGEN NO. 385-6