

Renewal $\frac{211}{11/12}$ T32S RBW

Found:

30" D. Fir N45W 50" S20W 73⁶
Faint Bort Scribble T32 RBW

Also unrecorded 1" Iron pipe
Not at Record Bearing & Dist

Renewal

Set Brass cap at sec cor MKB
County Surveyors office

T32S RBW

$\frac{52}{51} / \frac{51}{51}$
 $\frac{51}{51} / \frac{51}{51}$

1968

New Bearing Trees:

7" Tan Oak N85W 17²
Scribbled T32S RBW 52 CS BT

16" D. Fir N22E 26⁹
Scribbled T32S RBW 51 CS BT

15" Tan Oak S77E 18²
Scribbled T32S RBW 512 CS BT

Reblazed & Bort Scribbled
50" D. Fir S20W 43⁶
Scribbled T32S RBW 51 CS BT

1" Iron Pipe N20E 1⁹

7-12-68

~~Handwritten scribbles~~

#66

O.W. J.V.V.I.C.

C.S. File No. 54/65

DIETZGEN NO. 386-B