

Renewal

22/23
27/26

T325 RBW

Found:

10" Maple now 13" N12W 29³
Tree has been opened Face Burnt
but Fragmentary Scribbling Visible

10" D.F. now gone but Bearing + Dist
to old stump back good

2 Alder BTB Not Found

Call on creek 19³ East; RT This
time I find it to be about 92

Renewal

Set Brass cap at Sec cor MAR
County Surveyors office

T325 RBW

522/523
527/526

1968

DIETZGEN NO. 385 '6

New Bearing Trees:

10" Maple S19E 15⁴
Scribed T325 RBW S26 CS BT

3 1/2" D.F. S44W 21²
Scribed T325 RBW S27 CS BT

12" L. Oak N34E 61^E
Scribed T325 RBW S23 CS BT

13" L. Oak West 28⁵
Scribed T325 RBW S22 CS BT

3-8-68

~~James
[Signature]~~

963

O.K. J.W.B.

C.S. File No. 54/360-57