

Renewal

S35  
52/51

T335

R  
S  
W

Found:

15 X 18 Stone at Sec cor MAP  
C.C. on The South Face

Firmly in place.

18" D. Fir Now 20" S 20 W 25<sup>3</sup> (Rec 28<sup>3</sup>)  
Shows good Scar

10" Laurel Now 14" S 23<sup>3</sup> E (Rec S 22 E) 35<sup>3</sup>  
Shows Scabbing but Not ledgible

using Stone - 1 Bearing - 1 Dist

Renewal

Set Brass cap at Sec cor MAP.

County Surveyors of Rice

Daug. Co.  
T325 RBW

C.C. S35  
52/51

T335  
JOS. CO.

1968

New Bearing Tree.

8" D. Fir S 29 E  
Scribed T335 RBW S1 cc ss RT

Note

This cor lies 54' West of  
the standard cor of 35/36 T325 RBW

5-20-68  
J.W.B.  
J.W.B.  
J.W.B.

199  
O

O.K. J.W.B.

C.S. File No. 53/65 TH

DIETZEN NO. 385-6