

31 / 6 T31

T32S R2W

Renewal

Found

Broken Stake at Township cor. No
Marks visible

55" D. Fir ^{33"} now splintered stake S55E 33
Scribe visible C.C. T32S + other Marks

35" D. Fir now down 9' out of place S37W 9'
New Foot Hole. Found Scribe C.C. T32S R2W

15" D. Fir now rotten stump N70E 73

Renewal

Set Brass cap at Township cor. ~~N140~~
County Surveyors office

T31S
R S31 R
2 S1/S6 W
W C.C.
T32S

New Bearing Trees

38" D. Fir S37 W 33'
Scribed C.C. T32S R2W S1 CS BT

32" D. Fir S33 E 26'
Scribed C.C. T32S R1W S6 CS BT

Note: This cor lies 15' East
of 1/4 cor S31 T31S R1W

7-25-68

[Handwritten signature]

21 O.K. J.W. B.

C.S. File No. 54/28-4

DIETZGEN NO. 385-B