

Renewal 39/35 T315 RIW

Found

14" B. Oak now rotten stump S71 E 27²
(Rec 566 E 27²)

18" B. Oak now down rotten S20 W 18²
(Rec 524 W 48²)

Dug through rotten parts no scribe found.

Also Brass cap at 1/4 cor MAD.

General land office

T315 RIW

534 / 535

1922

Renewal

using Brass cap and both Dist. I
Mark new 373.

New Bearing Trees

14" D. Fir N 13 E 19²
Scribed 1/4 S 35 CS BT

13" D. Fir S 10 W 7²
Scribed 1/4 S 34 CS BT

9.24.68

O. N. J. V. B.

#119

C. S. File No. 534/71-51

DIETZGEN NO. 389-6