

T315 T305
Renew Township Cor R1W 51 | 56 T315 R1E.

Fd. O.B.T.s 25 follows -

ORIG. 7" Now 8" B. ORK N. 84° E. $39 \frac{6}{8}$ ft.

Now 7 ft. his way - we open & find scribe.

ORIG. 16" Now 17" Madrona S. 72° E. $22 \frac{4}{8}$ ft.

Down & out of position - scribe visible

on underside. After diligent

search we find 3" I.P. & Brass cap

approx 40 ft. Down hillside out

of ground. Reset Brass cap in

mound of stone at cor. point.

Mk. new B.T.

8" D. FIR S. $83 \frac{1}{2}^{\circ}$ W. $64 \frac{6}{8}$ ft.

Mkd. "T315 R1W 51 CS BT"

No other Live Trees or stamps close

for B.T.s - set $\frac{5}{8}$ " Iron Rod 20 ft.

N. & $\frac{5}{8}$ " Iron Rod 25 ft. N. of

cor. - This cor. Lies on steep

westerly slope approx 635 ft.

North of The E. $\frac{1}{4}$ cor. To Sec 1,

T315 R1W. - Rem #140

Oct 10, 1968

U.R.T.
J.H.
F.W.T.

G. R. Tracy

2143-T31-1W

C.S. File No.

54/71 594