

Renewal

9/10<sup>3</sup>

T315 RIW

Found:

14" Yew Scribe visible 595 E 38<sup>3</sup>  
T315 RIW 510 BT

26" D Fir Now Down N56E 152

No Trace of Brass cap (A23)  
By a logg<sup>r</sup>. Used Metal Finder  
To look for cap with no results

Renewal

Set Brass cap at Sec. cor M&D,  
County Surveyors office

T315 RIW

59/53  
510

1968

DIETZGEN NO. 386-6

New Bearing Trees:

11" Cedar N 37 W 96<sup>3</sup>  
Scribed T315 RIW 59 CS BT

10' D Fir N 36 E 105<sup>3</sup>  
Scribed T315 RIW 93 CS BT

Note

This cor lies on East  
Edge of Swampy Area.

(I could not chain between cor. b/c  
cause of water.

8-21-68

#74 O.K. J.W.V. 13.

C.S. File No. 64/71 93