

Benaval

10/11
15/14

T315 RIW

Found:

18" Hemlock now stump N65E 19L
 opened for service RIW 511 BT

8" Hemlock now 12" S41E 34L
 shows good scar

28" D. Fir now stump out of place
 No trace of NW BT.

Pter Search found 1923 Brass
 cap out of ground NW.

General land office

T312 RIW

S10/1511
 S15/514

1923

Benaval

Replaced Brass cap at sec. cor.

New Bearing Trees

18" D. Fir S 15 W 67L
 Scribed T315 RIW S15 CS BT

38" D. Fir N 16 E 41L
 Scribed T315 RIW S11 CS BT

12" R. Fir N 7 W 50L
 Scribed T315 RIW S10 CS BT

~~8-27-67~~
~~[Signature]~~
~~[Signature]~~
~~[Signature]~~

#82 O.K. J.W.B.

C.S. File No. 54/71-26

DIETZGEN NO. 385-6