

Renew  $\frac{1}{4}$  58/59 T315 RIW

Fd. 1923 G.L.O. BRASS cap firmly  
set & in good cond. & O.B.T.s as follows  
ORIG. 48" Now 58" Pine N. 30° E. 24  $\frac{1}{2}$  ft.  
2 live - scribe MKs. visible on unhealed  
Blaze.

ORIG. 40" Now 60" cedar N. 67° W. 30  $\frac{1}{2}$  ft.  
2 live - shows good scar - we do not open,  
do to large size of O.B.T.s - we MARK  
New B.T.s -

13" D. FIR N. 85° W. 6  $\frac{1}{2}$  ft.

Mkd. " $\frac{1}{4}$  58 CS BT"

16" D. FIR S. 60° E. 17  $\frac{1}{2}$  ft.

Mkd. " $\frac{1}{4}$  59 CS BT"

This cor. lies steep southerly  
slope

August 28, 1968

V.R.T.  
F.J.  
J.H.  
W.P.  
V.P.

V.R.T. Tracy

OW. J. W. B.

#83

C. S. File No.

54/71-109