

Renew  $\frac{1}{4}$  516 only T315 RIW

Fd. 1923 G.L.O. BRASS CAP in place

& STump of 1923 B.T.S 29 follows -

20" Now 26" FIR S. 51° W. 29° ft.

Now STump - shows SCAR

16" Now 16" FIR N. 17° W. 32  $\frac{3}{4}$  ft.

Now STump - scribe " $\frac{1}{4}$  516 BT" visible

we MK. new B.T.S -

12" Red FIR N. 30° W. 7  $\frac{2}{3}$  ft.

Mkd. " $\frac{1}{4}$  516 CS BT"

7" Red FIR S. 26° W. 18° ft.

Mkd. " $\frac{1}{4}$  516 CS BT"

This cor. lies on westerly

slope 87  $\frac{2}{3}$  ft. N. of the  $\frac{1}{4}$

cor. of sec 15 <sup>or. k</sup> agreeing with old

field notes.

August 28, 1968

J.P.T.  
F.W.J.  
J.H.  
W.P.  
V.P.

*J.P. Tracy*

#76 O.N. J.W.B.

C.S. File No. 54/71-110