

Renewal c.c.o.r

10
15

T315 RIW

found Brass cap

16 DFIR now stump hole N84E 27'

found no scribing

no trace of S, E, B.T.

note: This c.c.o.r lies 129' south of
The sec.c.o.r of 9&16 (That is
therecord.)

Found Brass cap at closing c.c.o.r. MKD.

US General Land Office Survey

cc | S10
S16 | S15

Renewal:

1922

new B.T.S.

5" DFIR N85¹/₂E 7'

scribed (S10 cc (S BT))

7" DFIR S66 E 19 E

scribed (T315 RIW S15 cc (S BT))

note: This c.c.o.r lies on top
of a flat ridge

B-29-68

F.W.J.
V.D.P.

[Signature]

#71

O. W. J. W. 19

C. S. File No. 54/71-113

DIETZGEN NO. 385-6