

Renewal $\frac{27}{34} | \frac{26}{35}$ T312 R1W

Found:

Brass cap of Sec car 17KD

General land office

T312 R1W

$\frac{527}{534} | \frac{526}{530}$

12" D. Fir Now rotten stump N30E 25⁺
Found scribe T312 R1W

36" D. Fir Now Sagg S10E 25⁺
Shows good scar

20" D. Fir Now 36" N17W (Belknap) 37⁹
Shows good scar

24" D. Fir Now down & rotten S38W 72

Renewal

New Bearing Trees

34" D. Fir N 66 E 10⁺
Scribed T312 R1W S26 CS 87

12" D. Fir S 24 1/2 E 18⁰
Scribed T312 R1W S35 CS 87

No Trees available in SW quad
old unit.

9-30-68

[Signature]

#91 O.W. Smith.

C. S. File No. 54/71-116

DIETZEN N. O. 385-6