

Renewal 591 T313 R1W

Found:

36" D. Fir Now 39" S75W 29 1/2  
shows good scar

36" D. Fir Now N30W 25 1/2  
shows good scar

Also Brass cap at 1/4 COR MK2

General Land office

T313 R1W

1/4 591

1923

Renewal

New Bearing Trees

9" Cedar S72W 5 1/2  
Scrided 1/4 59 CS BT

Note: This cor lies  
129 1/2 North of 1/4 cor 210 only

All Trees Tagged

9-3-68

~~JMB~~  
~~WCB~~  
~~JS~~

a.k. J.V.B.

#79

C. S. File No. 54/71-118

DIETZEN NO. 385-S