

Renewal

511/512  
514/513

T315 RIW

Found BRASS CAP and 1 BT  
NOTE: THIS COR. LIES in old BURN

36" DFIR now 38" SW 1/4 S63E 117

OPENED and Found scribbles of (513 RIW  
513 BT)

14" FIR now STOMP HOLE S58W 24<sup>4</sup>

NOTE: NO TRACE OF BEARING TREES  
IN THE NORTH

Found BRASS CAP AT SEC COR. MKE

US GENERAL LAND OFFICE SURVEY

T315 RIW

511/512  
514/513

Renewal

1423

new BT's:

8" DFIR S12E 12

scribbled (T315 RIW 513 (5 BT)

7" DFIR S63E 1/2 W 15<sup>2</sup>

scribbled (T315 RIW 514 (5 BT)

6" DFIR N63W 12<sup>4</sup>

scribbled (T315 RIW 511 (5 BT)

7" DFIR N7E 31<sup>2</sup>

scribbled (T315 RIW 512 (5 BT)

find  
0/5'

DIETZGEN NO. 385-6

#94/

From NO 54/71 E.W.S. W.P.P.R. - NO 9-4-68