

4/10/13 TB15 R/W

NOT Found ✓

IT had a 1923 BRASS
CAP. This cap was taken
out by a Logging unit,
The STUMPS are low.

We ran line between
Two Line Tags and
Found nothing

O.K. J.M.B.

CS 59/71 - 121