

534 | 535 T255  
53 | 52 T265 R8W

Renew Sec. Cor.

Fd. O.B.T.'s as follows -

orig. 15" now 36" Fir N. 75° E, 8<sup>6</sup>/<sub>16</sub> ft.

2 live - BARK SCRIBED POOR COND.

orig. 60" now 72" Fir S. 20° W, 42<sup>7</sup>/<sub>16</sub> ft.

2 live - No SCRIBE OR SCAR.

orig. 18" now 24" cedar N. 45° W, 42<sup>7</sup>/<sub>16</sub> ft.

2 live - shows good SCAR. S.E. O.B.T.

gone, 2<sup>d</sup> COR. point set 1" I.P.

& BRASS COP MKD. "COUNTY SURVEYORS

OFFICE 1968 T255 534 | 535  
53 | 52 T265

R8W" & MK. New B.T.s -

10" D. Fir N. 42° W. 34<sup>3</sup>/<sub>16</sub> ft.

Mkd. "T255 R8W S 34 CS BT"

10" D. Fir N. 41° E. 6<sup>7</sup>/<sub>16</sub> ft.

Mkd. "T255 R8W S 35 CS BT"

5" D. Fir S. 25° E. 18<sup>5</sup>/<sub>16</sub> ft.

Mkd. "S2 CS BT"

11" Maple S. 6° W. 15<sup>0</sup>/<sub>16</sub> ft.

Mkd. "T265 R8W S 3 CS BT"

This COR. Lies ON VERY STEEP

S.W. slope APPROX 165 ft. E. of

CREEK COURSE N.W.

July 25, 1968

V.R.T.  
J.H.  
Y.P.

*[Signature]*  
#26

O.R.S. No. 54/72<sup>5</sup>