

Renew Sec. Cor. $T25\ 5532\ |533$ R8W

Fd. O.B.T.s as follows -

Orig. 8" Now 20" cedar S. $60^{\circ}W$, 15²/₃ ft.

SNAG - Decayed center - No scribe fd.

Orig. 8" Now 24" cedar N. $20^{\circ}E$, 25¹/₂ ft.

2 live - we open & find "S33" scribe

& Reverse - ONLY Decayed Remains of

N.W. O.B.T. & NO TRACE of S.E. B.T.

2^d cor. point set 1" I.P. & BRASS cap

Mkd. "COUNTY SURVEYORS OFFICE

1968 T25S $\frac{532}{55}\ | \frac{533}{54}$ T26S R8W" &

Mk. New B.T.s -

20" cedar N. $24^{\circ}W$, 26⁶/₈ ft.

Mkd. "T25S R8W 532 cs BT"

9" Hemlock N. $34^{\circ}E$, 12²/₃ ft.

Mkd. "T25S R8W 533 cs BT"

7" Hemlock S. $9^{\circ}E$, 21⁸/₈ ft.

Mkd. "T25S R8W 54 cs BT"

9" Hemlock S. $40^{\circ}W$, 23⁹/₈ ft.

Mkd. "T26S R8W 55 cs BT"

This cor. lies on moderate easterly slope approx 100 ft. west of bench course N. & S.

August 22, 1968

#35 J.B. Tracy
#30-T26-8

V.R.T.
J.H.
V.P.

C.S. No. 54/72-11
O.K. J.W.D.