

531/532 T255 R8W
Renew Sec. Cor. 55/55 T265 R8W

Fd. @ B.T.s as follows -

ORIG (1881) 42" Now 60" FIR S, 10° E, 21 1/2 ft.

alive - BARK scribe visible - poor cond.

ORIG (1881) 34" Now 52" FIR S, 10° W, 26 1/4 ft.

alive - BARK scribe visible - Poor cond.

1876 BT 28" Now 40" FIR N, 70° E, 42 3/4 ft.

alive - No scribe or scar fd. - injured.

1896 BT 72" Now 82" FIR N, 8° W, 66° ft.

alive - BARK scribe visible - fair cond.

@ COR. point set 1" I.P. & BRASS cap
MKd, " COUNTY SURVEYOR'S OFFICE

1968 T255 531/532
56/55 T265 R8W " &

MK. New B.T.s -

11" Hemlock N, 12° E, 23 3/8 ft.

MKd, " T255 R8W 532 CS BT "

10" Hemlock N, 12° W, 18 3/8 ft.

MKd, " T255 R8W 531 CS BT "

7" Hemlock S, 65° W, 18 1/2 ft.

MKd, " 56 CS BT "

13" Hemlock S, 72° E, 26 1/4 ft.

MKd, " T265 R8W 55 CS BT "

This COR. Lies on precipitous
SE slope in large old fir &
young Hemlock.

985 2, 1968

* 46-7264

RT & S. No. 54/92-39

URT,
J.H.
J.W.B.