

Renew Sec. Co. R9W $\frac{S12}{S13}$ T25S R8W

2^d Cor point Fd. Sandstone called for
with 4 notches on S. & 2 notches on N. side
& O.B.T.s as follows -

orig. 60" now 68" FIR N. 70° E, 7 1/2 ft,

2 live - shows good scar - we do not open,

orig. 64" now 70" FIR S. 36 1/4° E, 21 1/2 ft,

2 live - shows good scar - we do not open -

(Note - the 2 above O.B.T.s were MK'd
before the closing cor. of sec. 5
& 18 was set chms north,

orig. 56" now 60" FIR S. 5 1/2° W, 23 1/2 ft,

2 live - shows good scar - we do not open,

we Rescribe "T25S R9W S13CS BT"

orig. 40" now 48" FIR N. 14° W, 30 1/2 ft,

2 live - shows good scar - we do not open,

we Rescribe "T25S R9W S12CS BT"

No matter how close - 2^d cor
point in place of Rock set 1" I.P.

& Brass cap MK'd "COUNTY SURVEYORS

OFFICE 1968 T25S R9W $\frac{S12}{S13}$ R8W"

This cor. lies on steep Brushy

S. slope approx. 430 ft south of

Ridge course NE & SW

Oct. 9, 1968

W. R. Tracy

J.R.T.
J.H.

C.S. File No.

54-122-44