

Renewal 35/36 T305 R2W

Found:

21' D. Fir Now Stump N26E 11<sup>2</sup>

24' D. Fir Now Down N19W 11<sup>9</sup>  
Tree Badly Splintered - Ture apart  
to find scribe of "BT"

Renewal

Set Brass cap at 1/4 cor MSD.

County Surveyors Office

T305 R2W

1/4 S35/S36

1968

New Bearing Trees

11" B. Fir S51E 13<sup>0</sup>  
Scribed 1/4 S36 CS BT

10" B. Fir N62W 15<sup>3</sup>  
Scribed 1/4 S35 CS BT

10-29-68

*[Signature]*

O.K. J.W.B.

#115

U. S. File No. 54/23-11

DIETZGEN NO. 385-6