

Renewal

26 R25
35/36

T30S R2W

Found

30" D Fir Now 38" N 60 E 8' 6"
Shows good Scar

18" D Fir Now Stump S 30 E 4' 3" 6"
opened for Scribe 187"

No Trace of N-W or SW BT's
(skid rd)

Also - unrecorded D Fir Now Stump 5'
High 12' North of cor faint Bark Scribe
on SE side T30S R2W S36
Possible start of cor tree then not used

Renewal

Set Brass cap at sec cor MHD.
County Surveyors office

T30S R2W

526/526
535/536

1968

New Bearings

6" Y Pine S 71 E 3' 1"
Scribed T30S R2W S26 CS BT

13" D Fir S 31 E 2' 2"
Scribed T30S R2W S30 CS BT

13" D Fir N 59 W 2' 3" 1/2"
Scribed T30S R2W S26 CS BT

Note
No good trees close in
(SW)

10-25-68

DIETZGEN NO. 385-6

#116

C.S. File No. 54/73-12