

Renewal

SI

T30S R2W

Found

8" P.F. Now stump S20E J0⁺
opened for scribe "BT"

Also stone at $\frac{1}{4}$ cor approx size
no marks visible

No Trace of SW BT

Renewal

Set Brass cap at $\frac{1}{4}$ cor MKD.

county surveyors office

T29S R2W

$\frac{1}{4}$ S1

T30S

1968

New Bearing Trees:

10 W. Fir S21E 23^z
scribed $\frac{1}{4}$ S1 CS BT

9' W. Fir S29W 28^z
scribed $\frac{1}{4}$ S1 CS BT

Note This cor lies 25^z East
of $\frac{1}{4}$ S 35 T29S R2W.

11-7-68

228-724-2

O.H. J. W. B.

#137

C. S. File No. 52/73-30

DIETZGEN NO. 388-6