

Renewal $\frac{33}{57}$ T29
T30 S 2W

Found

30" D. Fir Now 38" S 29 E 7°
Shows good seam

12" Cedar Now 36" S 22 1/2 W 13°
opened for 3/4" "15"

No trace of stone at sec. corner

Renewal

Set Brass cap at sec. corner MAP,
county Surveyors office

T29 S 2W

$\frac{33}{57}$

T30 S

1968

DIETZEN NO. 388-6

Next Bearing Trees

19" Hemlock S 67 W 39°
Scribbled T30 S 2W S 5 CS BT

8" Fir N 34 W 10°
Scribbled T29 S 2W S 33 CS BT

Note:
This corner lies 62 1/2 feet off

$\frac{32}{5}$

11-21-68

#40-T29-2

4152

C. S. File No. 54773 N. J. W. B.