

Renewal 5/9 8/9 T30S R2W

Found
 28" D. Fir Now Stk N31E 22'±
 Shows good seam partly exposed
 about 5' wide
 6" Maple Now 16" S60E 58'±
 Shows seam

40" D. Fir Now Down N8W 27'±

No Trace of SW ST


Also stone 15x10x15 firmly set
 at sec cor MKD with 5' markers
 south of markers East

Renewal
 Set brass cap at sec cor MKD
 county Surveyors office

T30S R2W
 55 / 59
 58 / 59
 1968

New Bearing Trees

10" D. Fir N 57 E 16'±
 Scribbled T30S R2W 59 CS ST
 9" D. Fir N 7 W 76'±
 Scribbled T30S R2W 55 CS ST
 14" D. Fir S 69 W 123'±
 Scribbled T30S R2W 58 CS ST

11-29-68


O. V.
 J. W. D.

#165

C. S. File No. 54/73-54

DIETZGEN NO. 385-S