

Renewal 20 | <sup>16</sup>/<sub>21</sub> T30S B2W

Found

30" D. Fir Now 37" N 25 E 2.5'  
shows good scar

24" D. Fir Now 32" S 72 E 12 E  
shows good scar

Also Stone 16 x 10 x 8 set firmly  
at sec cor with CC East Face

Renewal

Set Brass cap at sec cor MND,  
county surveyors office

T30S B2W

520 | <sup>516</sup>/<sub>521</sub> C.  
521 C.

1968

All Bearing Trees OK &  
Tagged.

Notes

This cor lies 100' E South of

<sup>12</sup>/<sub>20</sub> 16

12.5.68

*[Signature]*

OK  
J.W.B.

#167

S. File No. 54/73-12

DIETZEN NO. 388-6