

Renewal

20/21  
29/28

T30S R2W

Found:

10" D. Fir NOW 17' N76W 23<sup>0</sup>  
Shows good Scar

12" Larch NOW DOWN S60W 17<sup>2</sup>  
Found Reverse Scribbling - not  
enough to call letters & Rotted.

24" D. Fir NOW DOWN S4E 20<sup>5</sup>  
Rotted

15" Larch NOW DOWN N45E 33<sup>0</sup>  
Shows Faint Scar.

Renewal

Set Brass cap at Sec cor N&D  
County Surveyors office

T30S R2W

520 / 521  
527 / 528

1968

New Bearing Trees

6" D. Fir S50W 35<sup>6</sup>  
Scribed T30S R2W 529 CS BT

9" Cedar S70E 32<sup>5</sup>  
Scribed T30S R2W 528 CS BT

19" D. Fir N64E 36<sup>0</sup>  
Scribed T30S R2W 521 CS BT

Note: Cor Stone Not Found.

12-6-68

J. V. W. [Signature]

#172

C. S. File No. 54/75-64