

Revered

19/20
29

T305 B2W

Found

Broken Quartz Stone at closing Cor

No Trace of BT's

Also Found Stone 38³ West for
cor of 30/29 (no BT's)

I found these stones approx a year
ago.

Roseburg lumber has obtained from the
North & East to these points. Every
thing points to this being the correct
position for cor. From this info I
Revered

Revered!

Set Brass cap at Sec cor 1040

county surveyors office

T305 B2W/
C.C.
5/9/530
529
1970

New Bearing Trees

7" D Fir N 45 W 24²
Scribed T305 B2W 519 C.C. CS BT

6" D Fir S 15 E 18³
Scribed 529 CS BT

No other Trees available to the NE

Note

This cor lies 38³ ft East of

30/29

#175

O. W.
J. W. 57ⁿ
C. S. File No.

6-29-70
~~6-29-70~~
54/75-70