

Renewal

522/523

T295 RIW

Found

18" D. Fir New stump S30E 35°
opened for section

No trace of cor stone or SW
BT

cor lies in clear cut unit

Renewal

Set Brass cap at $\frac{1}{4}$ cor MRR
County Surveyors office

T295 RIW

522/523

1969.

Also steel Fence Post along
side of Brass cap.

New Bearing Traci

12" D. Fir S12E 178°
scribed $\frac{1}{4}$ 523 as BT

Also set $\frac{3}{4}$ " I. Rod North 15° &
 $\frac{5}{8}$ " I Rod North 25°

9-3-69

[Handwritten signature]

O.K.
J.W.B.