

Revised

10
16 | 15

T295 RIW

Found:

orig. 10" D. Fir S10E 185
Shows good scar

New BT's:

15" D. Fir New Down S22W 15-0

19" D. Fir New 15' N62E 32-0
Pitched over scribe visible

Also Brass cap & Stone at sec cor.
This cap marked in error. (1962) ~~BT~~

Revised

Re-marked Brass cap as follows:
county Surveyors office
T295 RIW

S10
S16 | S15
1962

New Bearing Tree

26' W. Fir S70W 47-0
Scribed T295 RIW S16 as BT

Note: This cor lies 128.7 East
of sec cor 16
9 | 10 (1962 Brass cap)

4-21-69

~~BT~~
~~BT~~
~~BT~~

D. N. J. W. B.

58

DIETZGEN NO. 385-6