

Renewal

23/21  
26/25

T295 R1W

Found:

10" D. Fir NOW 55" N23W 19<sup>1</sup>  
shows good Scar

20" W. Fir NOW 25" S64W 6<sup>E</sup>  
Rotten Face found def. in l. Scribe Marks

30" D. Fir NOW 37" N82E 18<sup>2</sup> (Rec 21<sup>1</sup>)  
shows good Scar

18x14 x10 Stone firmly set at  
Sec cor. No marks (chipped)

No Trace of SE BT.  
Renewal

Set Brass cap at Sec cor MKR.  
county Surveyors office

T295 R1W

523/521  
526/525

1969

Reblazed & Rescribed

29" W. Fir S64W 6<sup>E</sup>  
Scribed T295 R1W 526 CS BT

New Bearing Tree

13" R. Fir S83E 86<sup>2</sup>  
Scribed T295 R1W 525 CS BT

T23-69

J. W. M.  
J. W. M.  
J. W. M.

O.K. J. W. M.

40

C.S. No. 54/82-26