

Renewal

529
325

T29S R1W

Found:

18" D. Fir New Stump N9W 7⁹
shows good Scar

Also 24x7x6 Stone firmly set
at $\frac{1}{4}$ cor N52W $\frac{1}{4}$ on North Face

No Trace of SE BT because
of Rd.

Renewal

Set Brass cap at $\frac{1}{4}$ cor N52W

County Surveyors office

T29S R1W

$\frac{1}{4}$ 529
325

1969

DIETZGEN NO. 385-6

New Bearing Traces

6" Hemlock S29E 10⁷
Scribed N52S as BT

6" Hemlock N52 $\frac{1}{2}$ E 12⁶
Scribed N52 $\frac{1}{2}$ W as BT


Note

This cor lies 60° West of
Rd. on top of high cut,

5-8-69

#48

C. S. File No

54/82  50