

Review Sec Cor. RIW  $\frac{519}{530}$  T295 R1E

Fd. Cor. Stone Broken up in ground  
Mkd with "+" on Top & B.T.s as follows

Orig. 9" Non 11" Fir N, 83° E. 43  $\frac{1}{2}$  ft.

Down we open & find scribe & Reverse.

Orig. 16" Non 20" Fir S, 64° E. 13  $\frac{3}{4}$  ft.

alive - shows good scarp. - at cor.

point set 1" I.P. & BRASS cap mkd.

"COUNTY SURVEYOR'S OFFICE

1969 T295 RIW  $\frac{519}{530}$  R1E"

& MK. New B.T. -

7" W. Fir N, 42° E, 26  $\frac{1}{2}$  ft.

Mkd. "T295 R1E S19 CS BT"

good Blazed line from South

This cor. lies on moderate

S.E. slope in old growth Fir

Timber.

May 16, 1969

V.R.T.

J.G.H.

V.R.P.

W.P. JR.

V.R. Tracy

#99

#9 IE

0' 12" 5"

File No. 54782-60