

Renewal

$\frac{1}{4}$ $\frac{18}{19}$

T295 R1W

Found no Trace of 20X15X10 CORNERSTONE
and BOTH BTS ARE CUT BECAUSE THIS CORNER
LIES IN A LOGGING UNIT.

40" R FIR now 48" windfall STUMP N38E 92 FT
Shows a face

18" Cedar now 28" STUMP SOUTH 132 FT
OPENED AND FOUND SCRIBE OF A (B)

SET BRASS CAP AT 4 CORNER FROM
BEAR IN S & DIST FROM BOTH BTS. (M.K.D.)

COUNTY SURVEYORS OFFICE

T295 R1W

$\frac{1}{4}$ $\frac{518}{1969}$

NOTE: 5' metal fence post BY BC.
New Bearing Trees

6 Hemlock 564 E 204 1/2 FT

SCRIBED (4519CSBT)

28 Cedar 534 E 223 1/2 FT

SCRIBED (4519CS BT)

NOTE BEARING OBJECTS OUT RANGE
IN NORTH. PLUS THIS CORNER LIES
IN A LOGGING UNIT 25' WEST OF
CREEK.

M.K.D.
J.W.D.

5/21/69

KWJ

WRPJR 54/82

1/57 Year 20° TO THE EAST

DIETZEN NO. 385-6