

Review COR. #14 of HES 143 T295 R1E.

Fd. old cor. stone - Broken - in place
with MKs "HES 143" on pieces -
O.B.T.s -

ORIG. 14" Now 16" N, 40° E. 25 ± ft.

Now STUMP - scribe visible -

ORIG. 22" Now 28" FIR S, 39 1/2° W. 52 ft.

we open & find scribe & Reverse -

2⁺ cor. point in place of old stone

set 1" I.P. & BRASS cap MKd. "COUNTY

SURVEYOR'S OFFICE 1969 T295

COR. #14 T HES 143 R1E" Reset

stone along side - MK. New B.T. -

18" cedar N, 70° E. 54 ± ft.

Mkd. "14 HES 143 CS BT"

No other suitable Trees Near

This cor. lies on southerly

slope of hill approx. 50 ft

from Toe -

Dec. 15, 1969

V.R.T.
J.G.H.

A. R. Tracy

D. K.
5-2-63

#19

C. S. File No.

54/82-05