

Renew COR. #18 of HES143 T29S R1E
Fd STUMP of orig 20" now 21" Hemlock
COR. Tree - scribed "18 HES 143"
ON S.E. & "H 3" ON SW. - O.B.T.S
would fall in Roadway - we
Remove COR. STUMP & in its place
set 1" I.P. & BRASS cap MKd.
"COUNTY SURVEYOR'S OFFICE
1969 T29S COR #18 HES
143 R1E" & set 6 ft. steel
fence post along side. Mk. New
BT.

17" D. FIR N. 25° W. 74 ± ft.
MKd. "18 HES 143 CS BT"

This COR. lies ON East edge of
USFS access Road near intersection.
see Reverse side for Illustration.

Dec. 15, 1969

V.R.T.
J.G.H.

V.R. Tracy

O.V.
H.W.M.

#21 -

Over

C.S. File No. 54/82-96

DIETZGEN NO. 385-6

(X) ^{Neal}
D.T.

17/12
10/15
10/15
10/15

COR. #18
HES 143

