

Renew Cor. #17 of HES. 143 T295 R1E
Fd stump of orig. 24" Now 30" Fir
COR. Tree open & find " 143"
scribe & Reverse on East face
Both obts destroyed by Roadway.
Stump badly decayed - we Remove
enough wood from S. side to
set in center a 1" I.P. & Brass
cap MKd " COUNTY SURVEYORS
OFFICE 1969 T295 COR #17
{ HES 143 R1E " & MK. New B.T.s -

13" W Fir S. $36\frac{1}{2}^{\circ}$ W. 99' ft.

Mkd. " 17 HES 143 CS BT "

14" W. Fir N. 5° W. 145' ft

Mkd. " 17 HES 143 CS BT "

Note - COR. Lies on E. edge of
Road - New B.T.s on W. side of
Road.

Dec. 16, 1969

V.R.T.
J.G.H.

V.R. Tracy

D.K.
J.W.B.

#20 -

C.S. File No. 54/82-96