

N.F. HES. 144 T295 R1E

COR. # 8 would fall in  
Logging Road - No Trace of  
O.B.T.s OR COR. STONE -

---

COR. #12 Fd. STUMP of ONE  
O.B.T. - Does NOT FACE properly -  
could be ORIG. BEARING should  
have been S.W. instead of SE.  
we open & find "12 HES 144"  
SCRIBE - No Trace of old  
COR. STONE OR OTHER O.B.T.

DIETZGEN NO. 385-6

D.K.  
J.S.  
M.

CS 54/82-115