

**UNITED STATES PLYWOOD CORPORATION
OREGON DIVISION**

P.O. BOX 1328 • ROSEBURG, OREGON 97470 • PHONE 672-3331



Manufacturers of Weldwood Plywood
and Allied Products

July 21, 1966

Douglas County Surveyor
Douglas County Courthouse
Roseburg, Oregon

Gentlemen:

Please find corner renewal information for the following: Section Corner, 11, 14, and 10, Township 28 South, Range 2 West. Section Corner, 10, 15, 14, Township 28 South, Range 2 West. 1/4 Section Corner, Section 10 only, Township 28 South, Range 2 West. 1/4 Section Corner, Section 11 only, Township 28 South, Range 2 West. Section Corner 9, 10, 15, 16, Township 28 South, Range 2 West.

Yours very truly,

A handwritten signature in cursive script that reads "T.E. Shrum Jr.".

Thomas E. Shrum, Jr.
Logging Engineer
ROSEBURG OPERATIONS

TES:ap

attachs.

cc: USFS - Glide District
Glide Ranger Station
Glide, Oregon

FILED
RECEIVED

JUL 26 1966

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

Corner Renewal:

Section Corner: 11, 14, & 10 T28S R2W
(Area around section corner logged and burnt)

Found:

Orig. Brg. Tree: 42" Doug. Fir, N64°E, 14.5 ft.
Now: 40" Doug. Fir Stump, N64°E, 16.1 ft.
(Original scribe visible)
Orig. Brg. Tree: 32" Cedar, S45°E, 39.6 ft.
Now: 23" Cedar Stump, S45°E, 39.9 ft.
(Original face burnt out, rescribed)

Set:

Reset 2-1/2" Brass Cap. #28
28" Doug. Fir Stump, N69°W, 11.3 ft.

OK.
#33

Section Corner: 10, 15, & 14 T28S, R2W
(Area around section corner logged and burnt)

Found:

Orig. Brg. Tree: 42" Hemlock, S59°W, 9.9 ft.
Now: 52" Hemlock Stump, S57½°W, 12.7 ft.
(Orig. scribe visible - Rescribed)
Original Brg. Tree: 24" Hemlock Snag, N12°W, 29.0 ft.
(Burnt to stub)
Scribed 9-9-63: 8" Yew - Destroyed

Set:

Reset 2-1/2" Aluminum Cap. #29
36" Doug. Fir Stump, N50°W, 64.0 ft.

OK.
#34

1/4 Section Corner, Section 10 only T28S R2W

Area around 1/4 corner has been logged and the original bearing trees destroyed. Before logging, I buried 3/4" x 36" iron rod at 1/4 corner from original bearing trees.

From 3/4" x 36" rod; Set:

2-1/2" Aluminum Cap.
54" Doug. Fir Stump, N63°W, 48.5 ft.
40" Cedar Stump, S48°W, 15.3 ft.

OK.
#35

FILED
RECEIVED

JUL 26 1966

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.



1/4 Section Corner, Section 11 only T28S R2W

Area around 1/4 corner has been logged and the original bearing trees destroyed. Before logging, I buried 3/4" x 36" iron rod at 1/4 corner at location of 2" brass cap.

From 3/4" x 36" rod; Set:

Original 2" Brass cap.

72" Doug. Fir Stump, N44°E, 69.4 ft.

48" Cedar Stump, N83°E, 13.3 ft.

Section Corner: 9, 10, 15, 16 T28S R2W

Found:

22" Doug. Fir, N42°E, 120.5 ft. #30

17" Doug. Fir, N21½°W, 150.5 ft.

18" Doug. Fir, S39½°W, 135.0 ft.

Set:

2-1/2" Aluminum Cap.

(This corner falls in a rock pit)

FILED
RECEIVED

JUL 26 1966

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

