



THE ROBERT DOLLAR CO.

FOREST PRODUCTS DIVISION

AREA CODE 503 TELETYPE 830-0460
TELEPHONES
OFFICE 832-5050 SALES 832-5820
GLENDALE, OREGON

October 10, 1966

SAN FRANCISCO 4
HEAD OFFICE
311 CALIFORNIA STREET
NEW YORK 4, NEW YORK
1 BROADWAY
WASHINGTON 6, D. C.
716 TRANSPORTATION BUILDING

County Surveyor
Douglas County Courthouse
Roseburg, Oregon

Dear Sir:

I have restored the 1/4 Corner common to Section 23 and 24,
T31S, R9W, W.M.

I have found the following:

20" Douglas Fir BT - S60° E - 16.5' - Good Condition
14" Douglas Fir BT - S60°W - 7.9' - Destroyed in Clear Cut
Operation

For the corner I set a 1½" x 30" Iron Pipe, 28 inches in the
ground. I referenced for Section 23 a 10" Douglas Fir; N04°W,
15.3'; Scribed 1/4 S RS 749 BT.

Bearing tree was referenced with Staff Compass and Chain. Mag-
netic Variation 19½° East.

Yours very truly,

THE ROBERT DOLLAR CO.

T. H. Mehl, III
Registered Surveyor #749

FILED
RECEIVED

OCT 12 1966

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

#43

0

55/15-1