



THE ROBERT DOLLAR CO.

FOREST PRODUCTS DIVISION

AREA CODE 503 TELETYPE 830-0460

TELEPHONES

OFFICE 832-5050 SALES 832-5820

GLENDAL, OREGON

October 10, 1966

SAN FRANCISCO 4
HEAD OFFICE
311 CALIFORNIA STREET

NEW YORK 4, NEW YORK
1 BROADWAY

WASHINGTON 6, D. C.
716 TRANSPORTATION BUILDING

County Surveyor
Douglas County Courthouse
Roseburg, Oregon

Dear Sir:

I have found the Section Corner common to Section 18, 19 T31S, R9W, W.M. and Section 13, 24 T31S, R10W, W.M. to be in poor condition.

I have found the following evidence to the Corner:

- 48" Fir BT - S35° E - 8.6' - High Stump
- 8" Cedar BT - N65°E - 31.7' - Removed in Logging
- 40" Fir BT - S32°W - 18.5' - High Stump
- 24" Fir BT - N88°W - 21.8' - Snag Stump

For the Corner I have set a 1½" x 30" Iron Pipe 28 inches in the ground and referenced the following bearing trees:

- 5" Hemlock - N26°W - 8.2' - Scribed S13RS749 BT
- 4" Hemlock - N06°E - 5.1' - Scribed X (at breast Ht.) BT
- 12" White Fir - S30½°W - 52.5' - Scribed S24RS749 BT
- 13" Cedar - S25½°E - 51.9' - Scribed S19RS749 BT

Referencing was done with Staff Compass and Chain. Magnetic Variation 19½° E.

Very truly yours,

THE ROBERT DOLLAR CO.

T. H. Mehl, III
Registered Surveyor #749

FILED
RECEIVED

OCT 12 1966
THM;mt

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

#44
0

55/15-2