



# THE ROBERT DOLLAR CO.

## FOREST PRODUCTS DIVISION

AREA CODE 503 TELETYPE 830-0460  
TELEPHONES  
OFFICE 832-5050 SALES 832-5820  
GLENDALE, OREGON

May 19, 1967

SAN FRANCISCO 4  
HEAD OFFICE  
311 CALIFORNIA STREET  
NEW YORK 4, NEW YORK  
1 BROADWAY  
WASHINGTON 6, D. C.  
716 TRANSPORTATION BUILDING

County Surveyor  
Douglas County Courthouse  
Roseburg, Oregon

Dear Sir:

I have found the Section Corner common to Sections 30, 31, Township 32, S., Range 6 W., W.M. and Sections 25, 36, Township 32 S., Range 7 W., W.M. to be in poor condition.

I have found the following:

3/4" IP by Wendroth  
16" Alder S 64° 30' E, 84.9' by Wendroth  
Stump of 36" Fir BT N 24° W, 17 LK  
Bug Killed 48" Fir BT N 51° E 17 LK  
Blowdown 40" Fir BT S 52° E 14 LK  
4" Fir BT S 57° W, 39 LK destroyed by road construction  
12" Fir BT S 64° 08' W 39.0 Ft. destroyed by road construction

For the corner I set a 1-1/2" x 30" Iron Pipe 18 inches into the ground and referenced the following Bearing Trees:

4" Chinkapin N 40° E, 23.8' Scribed X (at breast ht.) BT  
7" White Fir S 78° E, 77.1' Scribed S 31 RS749 BT  
5" Ponderosa Pine S 28 3/4° E, 19.1' Scribed S31 RS749 BT

No bearing trees were available in the Northwest or Southwest quadrants. This is an area of snags, culls, and reproduction. After five years when this area is relogged, bearing trees can be securely established in these two quadrants.

Bearing Trees were referenced with Staff Compass and Steel Tape. Magnetic Variation 19° E. Witnessed by Paul Jonas, May 10, 1967.

FILED  
RECEIVED

MAY 22 1967

COUNTY SURVEYOR  
DOUGLAS COUNTY, ORE.

THM:mt

Very truly yours,

THE ROBERT DOLLAR CO.

T. H. Mehl, III  
Registered Surveyor #749

# 74 - 732-6  
# 43 - 732-7

C. S. File No. 55/15-3