



# THE ROBERT DOLLAR CO.

## FOREST PRODUCTS DIVISION

AREA CODE 503

TELEPHONES

OFFICE 832-5050 SALES 832-5820

GLENDAL, OREGON

HEAD OFFICE  
311 CALIFORNIA STREET  
SAN FRANCISCO 4

December 22, 1967

Mr. James W. Byron  
County Surveyor's Office  
Douglas County Courthouse  
Roseburg, Oregon

Dear Mr. Byron:

Thank you for bringing the renewal of the Standard corner of Sections 35 and 36, Township 32 South, Range 7 West, W.M., to my attention. I find the renewal was recorded in our files, but not sent to the courthouse.

I found the following original evidence at the corner:

30" Fir Stump N35°E - 10.0' - old hack marks outline face  
16" Fir Stump N47½°W - 24.0' - only root collar remains  
28" Fir Stump S07°E - 13.0' - bark scribing reads BT

I have set a 1¼" ID iron pipe for the corner, and have scribed the following bearing trees:

16" Douglas Fir N33°W - 17.5'  
12" Douglas Fir N27°W - 15.0'  
17" Live-Oak S0°30E - 32.0'

All bearings were taken with a staff compass; Magnetic Variation 19°00'E. Distances were measured with a steel tape. This corner was renewed in 1954; Information was verified by T. H. Mehl III, RS 749, December 21, 1967.

Very truly yours,

THE ROBERT DOLLAR CO.

Milner L. Larson  
Registered Engineer #3642

FILED  
RECEIVED

DEC 26 1967

COUNTY SURVEYOR  
DOUGLAS COUNTY, ORE.

#72

C.S.F. No. 55/15-5

Found &  
Used

35/36

T525 P2W

Found:

OBT - Possible  
32" Fir stump N30E 93  
old work No scribbling

Also

1" Iron Pipe at sea car?

New Bearing Trees

17" Live oak South 32°  
Scribed 3672 BT

19" D. Fir N28E 15°  
Shows good scar

19" D. Fir N33W 18°  
Shows good scar

This car unrecorded - original evidence  
possibly found on OBT mention above  
Work done by M. L. Larson (1959)

12-5-67

*[Signature]*

FILED  
RECEIVED

DEC 5 1967

COUNTY SURVEYOR  
DOUGLAS COUNTY, ORE.

#72

O.K.

J.V.V.

C.S. File No. 35/36-5

DIETZGEN NO. 385-6